# Sharon Town Hall Sharon, MA



## COLANTONIO INC. PROJECT # 18-3835





ARCHITECTURAL

ENGINEERS



TRAVERSE

#### samiotes

## The Sharon Standing

## **Building Committee**

## Weekly Activity Update

#### **Current Week – Activities**

- · Continue Mud/Tape 2<sup>nd</sup> Floor
- · Install Meeting Room Walls/Ceilings
- · Prime/Paint Walls 2<sup>nd</sup> Floor
- · Install ACT Ceilings 2<sup>nd</sup> Floor
- · Frame Stair #1 Ceiling
- · Rough MEP Stair #1 Ceiling
- · Install Sprinkler Drops 2<sup>nd</sup> Floor
- · Lighting Rough 2<sup>nd</sup> Floor
- · Mechanical Rough 2<sup>nd</sup> Floor
- · Layout Roof Top Condensers
- Install Cupola Metal and Rails
- Install Gutter Metal
- · Install Drywall 1<sup>st</sup> Floor
- · Mud/Tape Walls 1<sup>st</sup> Floor
- · Finish Sand Vault Walls and Ceilings
- · Prime/Paint Vault Walls and Ceiling
- Continue Shingle Siding South Elevation
- · Set Eversource Transformer



## Friday May 10, 2019 Report #33

#### Next Week - Activities

- Continue Prime/Paint Walls 2<sup>nd</sup> Floor
- · Continue ACT Ceilings 2<sup>nd</sup> Floor
- · Mud/Tape/Sand 2<sup>nd</sup> Floor Walls
- · Condenser Penetrations Flat Roof
- · Install Sprinkler Heads 2<sup>nd</sup> Floor
- · Mud/Tape Stair 1 and Stair 2
- Install Entrance Windows and Trim
- · Continue Mud/Tape 1<sup>st</sup> Floor Walls
- · Deliver Elevator, Controller and Frames
- · Continue Heat Pump Install 1<sup>st</sup> Floor
- · Excavate and Install Comcast Piping
- Strip Curbing East
- · Prep Sidewalks and Grade North West
- · Set Transformer Meter Supports
- · Pull Secondaries to Transformer

Subcontractor	Trade	# of Workers Onsite
Color Concepts	Painting	01
Titan Contractors Inc.	Site Work	01
Carlysle	Fire Protection	02
Marmello	Masonry	02
Griffin Electric	Electrical	05
General Insulation	Insulator	00
Colantonio Inc.	Carpenter	05
<b>United Site Services</b>	Site Sanitary	01
Colony Drywall	Framing	09
Colantonio	Labor	01
LaPan Mechanical	Plumbing	00
Division 15	HVAC	05
Delta Beckwith	Elevator	01
Alum/Glass Concepts	Aluminum Openings	00
Greenwood	Roofing	04
Cheviot	Ceilings	02
ВКА	Architect	02
Daedalus	Owner Representative	02
Colantonio Inc.	Construction Manager	03
TOTAL # Onsite This Week		46

#### <u>Safety</u>

- Safety Orientation for New Jobsite Workers Performed First Day of Work. Total Number of Onsite Workers/Visitors Orientated = 123
- All Workers Wear Proper PPE At All Times
- Fencing and Scrim Reviewed Each Week for Safety and Appearance
- Weekly Toolbox Talks are Conducted Within Each Trade And a Copy is Submitted to Colantonio Inc.
- Each Contractor Completes a Daily Work Report which Is Kept On File
- Construction Progress Meeting are Held Tuesday at 1PM.
- 189 Days With Zero Worker Accident
- 189 Days Without a Lost Time Accident

#### **Quality Control**

• Materials Delivered To The Site Cross Referenced Against Drawings, Submittals and Specifications prior to installation.

• Colantonio Inc and Subcontractor Review of Drawings and Specification Compliance Prior to Work Commencing

• 170 Random Quality Control Inspection Reports have been completed, of those: 02 remain as "Open" and "Non-Conforming"

#### **Miscellaneous**

- Colantonio Inc. subcontractor meeting to be held on Tuesdays at 10AM
- Controls Integration Meeting Tuesday May 14, 2019 12PM

## Weekly Activity Update



**Second Floor Meeting Room** 



## Friday May 10, 2019 Report #33



#### Second Floor Meeting Room



**Lighting Layout** 

**First Floor MEP Rough** 

## Weekly Activity Update



**Cupola Railings** 

### Friday May 10, 2019 Report #33



**Vault Interior Walls** 





**Ceiling Grid Installation** 

**Transformer Delivery**