Sharon Town Hall Sharon, MA



COLANTONIO INC. PROJECT # 18-3835













The Sharon Standing

Building Committee



Weekly Activity Update

Current Week - Activities

- · Final Coat and Sand 1st Floor
- · Prime Paint 1st Floor Walls
- · Paint Accent Walls 2nd Floor
- Receive Millwork and Countertops
- Begin Millwork Install
- Continue Ceiling Grid Installation
- Continue Lighting Installation
- Continue Elevator Installation
- Install Elevator Doors and Controls
- Continue Tile and Grout Bathrooms
- Begin Excavation for Septic/Leech Field
- Inspection of Excavation Depth
- Receive Exterior Granite Blocks
- Continue Entrance Framing
- Begin East Elevation Window and Siding
- · Form and Place South Sidewalks
- Begin Column Wraps South Sidewalk
- · Continue Heat Pump Install 1st Floor
- · Continue Fire Suppression Install Vaults

Friday June 7, 2019 Report #36

Next Week - Activities

- . Continue Prime/Paint Walls 2nd Floor
- · Continue Prime/Paint Walls 1st Floor
- · Continue ACT Grid 2nd Floor
- Begin ACT Grid 1st Floor
- . Prime/Paint Stair #2
- · Continue Elevator Installation
- Continue Septic/Leech Field
- Begin Installation of Granite Blocks
- · Continue Millwork 2nd Floor
- · Continue East Elevation Siding
- Excavate for Gas Service
- Gas Service Installation
- · Install Water Heater 1st Floor
- · Receive Bathroom Finishes 2nd Floor
- · Continue Electric Devices 1st Floor
- Begin Installation of Aluminum Track

		" () " 0 "
Subcontractor	Trade	# of Workers Onsite
Color Concepts	Painting	01
Titan Contractors Inc.	Site Work	03
Carlysle	Fire Protection	02
Marmello	Masonry	01
Griffin Electric	Electrical	02
General Insulation	Insulator	00
Colantonio Inc.	Carpenter	02
United Site Services	Site Sanitary	01
Colony Drywall	Framing	04
Colantonio	Labor	01
LaPan Mechanical	Plumbing	01
Division 15	HVAC	04
Delta Beckwith	Elevator	02
Alum/Glass Concepts	Aluminum Openings	00
Greenwood	Roofing	01
Cheviot	Ceilings	01
Superior	Caulking	00
Capital Carpet	Tile	03
A.P. Dailey	Millwork	01
Federal	Concrete	06
ВКА	Architect	02
Daedalus	Owner Representative	02
Colantonio Inc.	Construction Manager	03
TOTAL # Onsite This Week		43

Safety

- Safety Orientation for New Jobsite Workers Performed First Day of Work. Total Number of Onsite Workers/Visitors Orientated = 123
- All Workers Wear Proper PPE At All Times
- Fencing and Scrim Reviewed Each Week for Safety and Appearance
- Weekly Toolbox Talks are Conducted Within Each Trade And a Copy is Submitted to Colantonio Inc.
- Each Contractor Completes a Daily Work Report which Is Kept On File
- Construction Progress Meeting are Held Tuesday at 1PM.
- 209 Days With Zero Worker Accident
- 209 Days Without a Lost Time Accident

Quality Control

- Materials Delivered To The Site Cross Referenced Against Drawings, Submittals and Specifications prior to installation.
- Colantonio Inc and Subcontractor Review of Drawings and Specification Compliance Prior to Work Commencing
- 175 Random Quality Control Inspection Reports have been completed, of those: 02 remain as "Open" and "Non-Conforming"

<u>Miscellaneous</u>

- Colantonio Inc. subcontractor meeting to be held on Tuesdays at 11AM
- Eversource On Site June 8th for Roadside Work
- Gas Service Street Opening Permit Released Week of June 10th
- Generator Relocation Friday June 21st at 12PM
- Excavated Soils Dumpster Hauled Off Site



Millwork Installation



Sidewalk Installation



Millwork Installation



Generator Pad





Leech Field



Exterior Granite Delivery

Leech Field



Elevator Machine Room