Sharon Town Hall Sharon, MA



COLANTONIO INC. PROJECT # 18-3835





ARCHITECTURAL

ENGINEERS



OLANTONIO

40 YEARS OF BUILDING RELATIONSHIPS

TRAVERSE TRAVERSE

samiotes

The Sharon Standing

Building Committee

Weekly Activity Update

Current Week – Activities

- · Prep Sidewalks
- · Form Sidewalks
- Install Light Pole Bases
- · Install UG Conduit
- · Continue Paint of Trim and Siding
- · Install ACT Tiles 2nd Floor
- Install ACT Cuts 1st Floor
- · 2nd Floor on Permanent Power
- · Install Elevator Exhaust
- Continue Wood Ceiling 2nd Floor
- · Install Registers 1st Floor
- Install Lobby Lighting 1st Floor
- · Install Carpet tile 2nd Floor
- · Install LVP 2nd Floor
- · Install Base 2nd Floor
- · Finish ACT Install 2nd Floor
- · Finish Bathroom Tile
- · Load in Lobby Tile
- · Remove Temp Electric 2nd Floor

Saturday July 13, 2019 Report #41

Next Week - Activities

- · Continue Testing Lights and Power
- · Continue Fire Alarm Device Install
- · Place Sidewalk South
- · Back Fill UGE for Site Lighting
- · Install Granite Curbing East
- · Gravel for Parking Lot
- · Install Lobby Tile
- · Received and Install Granite Pavers
- · Install VCT 2nd Floor
- · Continue Wood Ceiling Installation
- · Install 1st Floor Millwork
- · Install ACT Cuts 1st Floor
- · Paint Stairwell Walls and Railings
- · Install Gas Meter
- · Install Stairwell Light Stair #2
- · Heat Pump Start Ups
- Install Toilet Partitions
- Install Aluminum Doors/Glass

Subcontractor	Trade	# of Workers Onsite
Color Concepts	Painting	02
Titan Contractors Inc.	Site Work	03
Carlysle	Fire Protection	00
Marmello	Masonry	02
Griffin Electric	Electrical	04
General Insulation	Insulator	02
Colantonio Inc.	Carpenter	04
United Site Services	Site Sanitary	01
Colony Drywall	Framing	01
Colantonio	Labor	01
LaPan Mechanical	Plumbing	00
Division 15	HVAC	07
Delta Beckwith	Elevator	01
Alum/Glass Concepts	Aluminum Openings	03
Greenwood	Roofing	00
Cheviot	Ceilings	03
Superior	Caulking	00
Capital Carpet	Tile	02
Pavilion Floor	Carpet Tile	02
Santangelo Floors	VCT/LVP/Base	03
ВКА	Architect	02
Daedalus	Owner Representative	02
Colantonio Inc.	Construction Manager	03
TOTAL # Onsite This Week		48

<u>Safety</u>

- Safety Orientation for New Jobsite Workers Performed First Day of Work. Total Number of Onsite Workers/Visitors Orientated = 136
- All Workers Wear Proper PPE At All Times
- Fencing and Scrim Reviewed Each Week for Safety and Appearance
- Weekly Toolbox Talks are Conducted Within Each Trade And a Copy is Submitted to Colantonio Inc.
- Each Contractor Completes a Daily Work Report which Is Kept On File
- Construction Progress Meeting are Held Tuesday at 1PM.
- 234 Days With Zero Worker Accident
- 234 Days Without a Lost Time Accident

Quality Control

• Materials Delivered To The Site Cross Referenced Against Drawings, Submittals and Specifications prior to installation.

 Colantonio Inc and Subcontractor Review of Drawings and Specification Compliance Prior to Work Commencing

• 199 Random Quality Control Inspection Reports have been completed, of those: 02 remain as "Open" and "Non-Conforming"

Miscellaneous

- Colantonio Inc. subcontractor meeting held on Tuesdays at 11AM
- Columbia Gas Underground Service Installed 07/03/2019
- Granite Paver Delivery July 18th
- Security Camera Install and Adjust Monday July15 9:30am

Weekly Activity Update

Saturday July 13, 2019 Report #41




Wood Ceiling Installation



Staff Break Room



Wood Ceiling Installation



Work Storage Office 210B

Weekly Activity Update

Saturday July 13, 2019 Report #41



Carpet Installation



Elevator Exhaust Install



Carpet Installation



Washed Granite