Sharon Town Hall Sharon, MA



COLANTONIO INC. PROJECT # 18-3835













The Sharon Standing

Building Committee



Weekly Activity Update

Saturday October 19,2019 Report #53

Current Week – Activities

- · Install Drainage East Chestnut Street
- · Infill OTH Basement Depression
- · Install DMH#6 and Piping
- . Install CB #5 and CB#6
- Selective Demolition of Brick Sidewalk
- Install EMB Sonotubes for Granite Posts
- Install Colored Escutcheon Plates
- · Install Vestibule Entrance Mat

Next Week - Activities

- Install Door Film New Town Hall
- · Excavate for UGE Conduit
- . Install Site Bollard Bases
- · Backfill and Sub grade West
- Strip South Main Street Forms
- · Install and Place Concrete for Flagpole
- · Continue Site Drainage
- Prep Entrance Sidewalks
- · Install Granite Curbing
- · Install Plantings West and Northwest
- . Install Loam and Seed West
- Relocate South Main Street Fencing
- · Install Select Board Door Hardware

Subcontractor	Trade	# of Workers Onsite
Reed Associates	Surveying	02
Titan Contractors	Site	05
Briggs	Testing	01
Aluminum Glass	Glass and Frames	00
Division 15	HVAC	01
Colantonio	Labor	00
Labidini	Landscaping	03
Pavilion	Flooring	02
Carlysle	Fire Protection	01
BKA	Architect	02
Daedalus	Owner Representative	03
Colantonio Inc.	Construction Manager	03
TOTAL # Onsite This Week		24

Safety

- Safety Orientation for New Jobsite Workers Performed First Day of Work. Total Number of Onsite Workers/Visitors Orientated = 161
- All Workers Wear Proper PPE At All Times
- Fencing and Scrim Reviewed Each Week for Safety and Appearance
- Weekly Toolbox Talks are Conducted Within Each Trade And a Copy is Submitted to Colantonio Inc.
- Each Contractor Completes a Daily Work Report which Is Kept On File
- Construction Progress Meeting are Held Tuesday at 1PM.
- 314 Days With Zero Worker Accident
- 314 Days Without a Lost Time Accident

Quality Control

- Materials Delivered To The Site Cross Referenced Against Drawings, Submittals and Specifications prior to installation.
- Colantonio Inc and Subcontractor Review of Drawings and Specification Compliance Prior to Work Commencing
- 231 Random Quality Control Inspection Reports have been completed, of those: 03 remain as "Open" and "Non-Conforming"

Miscellaneous

- New Drainage Structures Delivered to the Site
- Flagpole Sleeve Delivered to the Site
- South Main Street Sidewalk Reopened



Asphalt Patch – E. Chestnut



Sidewalk Layout

Install Dry Well



Vestibule Entrance Mat